



JEWELL AVIATION

(573) 888-5846

(573) 888-0228

P.O Box 623 - 418 AIRPORT ROAD - KENNETT, MO. 63857

Effective: June 22, 2018

SHOP RATE

per. hr. \$ **85.00**

ENGINE MAJORS

Continental 0-200 - Labor Only	2,700.00
Average parts - engine only - no accessories	8,500.00
Continental 0-300 - Labor Only	3,000.00
Average parts - engine only - no accessories	9,000.00
Continental IO-360 - Labor Only	3,200.00
Average parts - engine only - no accessories	13,750.00
Continental TSIO-360-Labor Only	3,700.00
Average parts- engine only – no accessories	15,500.00
Continental 0-470 - Labor Only	3,250.00
Average parts - engine only - no accessories	12,750.00
Continental IO-470 - Labor Only	3,500.00
Average parts - engine only – no accessories	12,750.00
Continental IO-520 - Labor Only	3,500.00
Average parts - engine only - no accessories	13,500.00
***Add Approximately \$5000 for new Cam and Crank Gear w/Starter Adapter	
Continental IO-550 – Labor Only	3,500.00
Average parts - engine only - no accessories	14,000.00
Continental TSIO-520 - Labor Only	3,700.00
Average parts - engine only - no accessories	17,500.00
Continental GTSIO-520 – Labor Only	4,500.00
Average parts – engine only – no accessories	29,000.00
Lycoming 0-235 - Labor Only	2,500.00
Average parts - engine only - no accessories	8,800.00
Lycoming 0-320 - Labor Only	2,500.00
Average parts - engine only - no accessories	8,800.00
Lycoming 0-360 - Labor Only	2,500.00
Average parts - engine only - no accessories	9,200.00
Lycoming IO-360 - Labor Only	2,700.00
Average parts - engine only - no accessories	9,200.00
Lycoming O-540 – Labor Only	3,000.00
Average parts - engine only – no accessories	12,400.00
Lycoming IO-540 - Labor Only	3,250.00
Average parts - engine only - no accessories	12,800.00
Lycoming TIO-540 – Labor Only	3,800.00
Average parts – engine only - no accessories	16,000.00
Lycoming IO-720 – Labor Only	4,500.00
Average parts - engine only - no accessories	22,000.00

NOTE: The price for an engine overhaul does not include removal or re-installation of the engine. Certain turbo-charged and specialized engines may vary. Add approx. \$500 for 76 series models